

## SAMPLE PLAN ALTERATION FORM

**Project Name and Number:** 4<sup>th</sup> Avenue and Gambell Parking Lot; TDD: 11-04-0001

**Material to be Sampled:**

Surface soil and background soil.

**Measurement Parameters:**

Analyses of surface soil and background soil for volatile organic compounds (VOCs).

**Standard Procedure for Field Collection and Laboratory Analysis (cite references):**

Collect one background surface soil sample and one background subsurface soil sample for each 5-foot interval in which source/target samples were collected. These samples were to be analyzed for VOCs.

**Reason for Change in Field Procedure or Analytical Variation:**

A background surface soil sample was not collected due to the entire sample location being covered in asphalt and the upper 6-inches of soil possibly being affected by the asphalt covering.

A 50-foot background subsurface soil sample was not collected due to ground water being encountered at approximately 43-feet bgs in the first borehole drilled (BH01) and 39.5-feet in the second borehole drilled (BK01). Drilling at both of these borings was terminated at 45-feet bgs. However, with the exception of BH02, all other site-related borings were drilled to 50-feet.

**Variation from Field or Analytical Procedure:**

A background surface soil sample was not collected. Surface soil samples will be compared to the 0 to 5-foot background subsurface soil sample.

A background 45 to 50-foot background subsurface soil sample was not collected. Subsurface soil samples collected from 45 to 50-feet will be compared to the 40 to 45-foot background subsurface soil sample.

**Special Equipment, Materials, or Personnel Required:**

No special equipment, materials, or personnel were required for this alteration to the sampling plan.

CONTACT	APPROVED SIGNATURE	DATE
<b>Initiator:</b> Jeff Fetters		1-22-13
<b>START PL:</b> Linda Ader		1-22-13
<b>EPA TM:</b> Brandon Perkins		1/22/2013
<b>EPA QA Manager :</b> Gina Grepogrove		1/23/2013

USEPA SF



1397836